

Repair and Replacement of Hunter Cabin Roof And Log House Porch Repair



Photo E. The porch on the historic log house was reconstructed on the west side to remove its weight from the log wall, now resting on its own foundation. The south side was repaired. The lumber is rough sawn to be like the original. Logs were skidded to sawmill, cut into lumber and hauled to the site.



Photo A. The historic Hunter's cabin or north cabin had developed leaks in the roof causing water damage inside. In Winter/Spring of 2016, high winds blew dead bug trees onto the roof which caused structural damage.



Photo B. With the structural damage to the rafters and chimney repaired, the roof was resurfaced with 4X8 sheets of OSB.



Photo C. With a new stronger subroof, a water tight barrier was applied as an underlayment before installing the metal roof.



Photo D. The new ProRib roof was installed in November of 2016. The roof is a dark brown color to match the color and design of the old historic log house.